



**STÖGER**  
AUTOMATION

Technical cleanliness in  
production and assembly

Lorenz Stöger, STÖGER AUTOMATION GmbH

## I. Introduction

### ➤ Sectors where cleanliness is crucial

- e.g. Medical technology
- Pharmaceutical industry
- Automotive
- Electronics
- Aviation




### ➤ Why is cleanliness important?



- Hygiene
- Functionality
- Optical appearance



### ➤ Different requirements for cleanliness demand different approaches




Components and factors requiring cleanliness



## II. Challenges

### Screws





- Quality of the thread




- Screw geometry

- Dimensional accuracy / Tolerances
- e.g. slot or screw head not centered



Screw



- coating or encapsulation of screws
- dirt particles in the bulk material
- abrasion (e.g. in the packing material, during transport etc.)







Foto: Arnold Umformtechnik GmbH



## Work piece



- Tolerances in the work pieces
  - faulty bore hole diameter
  - inaccurate positioning of the bore holes
  - tolerances due to material (plastic, cast materials, coatings)
- Contamination during production processes
  - e.g. caused by prior treatment:
    - drilling
    - countersinking
    - thread cutting
    - coating



**STÖGER**  
AUTOMATION

Screwdriving system



nose piece

screwdriving tool


positioning accuracy

air current

feed system



screwdriving process





www.stoeger.com

## Environment



- ventilation / air conditioning / heating
- travel paths (forklift trucks, transport systems ...)
- staff (hair, particles of skin, food crumbs, dirty shoes ...)
- clothing (fluff, oil, dust, chips ...)
- cleaning of the work environment







### III. Requirements for the screwdriving process

#### Prevention of contamination of components

- 1) comply with standards or clean room classes
- 2) optimal adjustment of screwdriving parameters
  - a) cycle time
  - b) duration of screwdriving process
  - c) screwdriving position
  - d) rotational speed, torque
  - e) tool stroke speed
  - f) finding the screw head engagement
  - g) hard or soft material (e.g. metal or plastic)





## Relevant standards

### VDA 19 Part 2

- deals with technical cleanlines, especially with particles of 15–1.000 µm
- measures to minimize / avoid the following in the entire process chain
  - Particles intruding from outside
  - Particles intruding through the process chain
  - Particles developing during the process

### ISO 14644 (clean room)

- Standard for clean rooms and relevant clean room areas

Reinraumklassen nach ISO 14644-1

Klasse	Partikel je m <sup>3</sup> ;					
	0,1 µm	0,2 µm	0,3 µm	0,5 µm	1,0 µm	5,0 µm
ISO 1	10	2				
ISO 2	100	24	10	4		
ISO 3	1.000	237	102	35	8	
ISO 4	10.000	2.370	1.020	352	83	
ISO 5	100.000	23.700	10.200	3.520	832	29
ISO 6	1.000.000	237.000	102.000	35.200	8.320	293
ISO 7				352.000	83.200	2.930
ISO 8				3.520.000	832.000	29.300
ISO 9				35.200.000	8.320.000	293.000

STÖGER

Grafik: Wikipedia

## Screwdriving parameter

### a) Cycle time

The lower the cycle time the more particles can enter the screwdriving process: more vibration in the feed bowl, screw has to be fed faster into the system, thus harder surface contact, causing particles to chip off as well as abrasion etc.

### b) Convolutions (threads)


The more revolutions per screw-in length are needed the more abrasion will be caused

### c) Screwdriving position

In processes for screwdriving in an upward direction particles will fall away from the work piece due to gravitation. Even screwdriving in a horizontal direction may bring better results.

### d) Number of revolutions

A higher speed results in more abrasion due to higher friction.



### e) Tool stroke speed


The higher the tool stroke speed the more force will be exerted on the connection, causing more abrasion or creation of particles.


### f) Finding the screw head engagement

While the bit tries to engage in the slot, a lower revolution speed will ensure a smooth contact, thus reducing abrasion and the creation of particles.

### g) Hard / soft materials

Plastic materials may heat up too much, e.g. due to high speed, causing the formation of strings. Coating material of screws may result in abrasion.





#### IV. Possible solutions

- 1) Use of standardised / true-to-size screws
- 2) Use of cleaned screws
- 3) Use of suitable feed units
- 4) Use of particle sluices
- 5) Use of vacuum screwdrivers, avoiding magnetic bits
- 6) Use of Pick & Place systems
- 7) Adjusting the screwdriving parameters
- 8) Use of magazines for screws
- 9) Optimum positioning of the feed units (no air current)
- 10) Use of suitable system combinations for screwdriving processes
- 11) Preventive measures


**STÖGER**  
AUTOMATION



## True-to-size screws



### 1) Use of standardised / true-to-size screws

- Quick positioning of the bit in the screw slot
- Gentle on the screw heads
- No scratches or other damage



## Cleaned screws

- Use of cleaned screws
  - Use of cleaned screws (e.g. CLEANCON® by Arnold Umformtechnik), which have been cleaned repeatedly during and after the production process and packed accordingly.




## Bowl feeder

- Suitable for most fasteners
- Screws are sorted several times
- Vibration may cause abrasion and the creation of particles




- Improved situation when using hoppers and linear tracks: the hopper serves as a buffer for the screws until their quantity in the feed bowl has dropped below a defined level; thus fewer screws in the feed bowl and consequently less friction. Feed bowl vibrates only when linear track has to be refilled.






### Step feeder

- Suitable for most fasteners
- Screws are transported into the rail of the singling mechanism through various steps
- Only this rail vibrates in order to position the screws correctly
- Screws are sorted several times
- The use of a hopper reduces the filling level in the step feeder bowl. Refilling will be necessary only when the quantity has dropped below a defined level.






## Segment feeder

- Suitable for most fasteners
- The sorting process is realised by an oscillating segment. The fasteners are transported via a linear track which is positioned diagonally.
- System works without vibration
- Screws are processed multiple times, which may cause abrasion
- The use of a hopper ensures that fewer screws are in the bowl, which could cause friction between the fastening elements. Refilling will be necessary only when the quantity has dropped below a defined level.






## channel feeder 100


- Suitable for screws (head-shaft ratio important!), also for coated and encapsulated versions
- System works without vibration and sorting air current
- Each screw is sorted only once: a few screws only are fed from a bunker and placed on a transport band which leads to a sorting rail, ending in an exit rail. Only actually required screws are transported.




**STÖGER**  
AUTOMATION

Particle sluice







### Particle sluce



Number of particles measured with and without using a particle sluce

## Vacuum screwdriver

- Extraction of particles due to vacuum in screwdriving system
- Magnetic bits less suitable in clean environment, as metallic particles will be attracted




## Pick & Place-Systems

- Use of Pick & Place Systems
  - advantage: no particles are blown to the work piece, as no transport air current
  - disadvantage: higher cycle times
  - disadvantage: more space required at screwdriving location as feed unit has to be positioned near screwdriving unit



**STÖGER**  
AUTOMATION

Screwdriving parameters






## Feeding from a magazine

- Feeding screws from a magazine
  - relatively flexible system; no transport air current required, no intrusion of foreign particles
  - feeding from earlier mentioned feed systems
  - possible only with robot or axle/gantry system





image: drum magazine; possible also hose and bar magazines





**STÖGER**  
AUTOMATION

Placement




## Combinations



## Care and maintenance

- Precautions:
  - Regular cleaning of screwdriving system and feed unit
  - Regular maintenance of screwdriving system and feed unit




## Conclusion

### High degree of cleanliness means

- Lower susceptibility of failures in work piece and system
- Fewer customer complaints, higher customer satisfaction
- Lower costs

There are different approaches to achieve desired result. Our experts will be pleased to advise you to work out the optimal solution for your application.





**STÖGER**  
AUTOMATION



Thank you for your attention

STÖGER AUTOMATION GmbH

Gewerbering am Brand 1

82549 Königsdorf

Telefon: +49 8179 99767 0

Telefax: +49 8179 99767 50

E-Mail: [info@stoeger.com](mailto:info@stoeger.com)

[www.stoeger.com](http://www.stoeger.com)

